

Hendricks Mill Building Photo Logs




Figure 1: Approximate Dimensions of Hendricks Mill roof (not to scale).



View of Northwest side of building (2015). Letter notations correspond to Figure 1.



View of Northeast side of building (2015). Letter notations correspond to Figure 1.



View of Southwest and Southeast sides of building.




View of underside of main roof structure (2015).




Original roof planking and remnants of pre-existing rolled roofing (1986).



Sheathing installed over original roof planking and pre-existing rolled roofing; note aviation markings (1986).



Sheathing installed over original roof planking and pre-existing rolled roofing; note aviation markings (1986).



Sheathing installed over original roof planking and pre-existing rolled roofing (1986).